



**WIPE NEW®
HEADLIGHT RESTORE**

DESCRIPTION AND USES

Rust-Oleum® Wipe New® Headlight Restore is a long-lasting solution that restores clarity to aging and fogging headlights.

PRODUCT FEATURES AND BENEFITS

- Restores illumination and visibility
- Easy-to-use, one wipe solution
- Long lasting shine – protects through 100 car washes

PRODUCTS

SKU	DESCRIPTION
397048	Wipe-New Headlight Restore Kit

KIT CONTENTS

- 1 - Wipe New Wipe-It™ 0.5 fl. oz.
- 1 - Professional Lens Polishing Pad
- 1 - Microfiber Cloth
- 1 - Pair Nitrile Gloves

PRODUCT APPLICATION

READ ALL INSTRUCTIONS CAREFULLY BEFORE STARTING PROJECT

APPLICATION CONDITIONS

Use when temperatures are between 40°F and 90°F (4°C and 32°C). Use in well-ventilated and covered areas away from the sun. Do not apply Wipe New to hot surfaces or in direct sunlight. Ensure surface is clean, dry and cool to ambient temperature before applying Wipe New.

SURFACE PREPARATION

Prep the exterior of all lenses intended for application at the same time so that one Wipe-It can be used to treat all lenses. Once the Wipe-It is opened it begins to cure. Do not open the Wipe-It until needed and complete the application within a few minutes.

Wash the intended surface thoroughly with a standard soap, cleaner or car wash (free of wax, moisturizers or other additives). Rinse and let dry. For best results, apply a degreaser to heavily worn areas to fully clean the surface.

To determine whether you need to use the Professional Lens Polishing Pad, pour water onto your headlight lens. The way the lens looks when wet is the way it will appear once treated with Wipe New. If the lens appears crystal clear when wet (and hazy only when dry), then you do not need to use the Lens Polishing Pad. Simply wash the lens with soap and water, rinse, and apply Headlight Restore. If the lens appears cloudy or hazy when wet, the Lens Polishing Pad will be required.

Wet the headlight lens with water and use the green side of the Lens Polishing Pad to wet sand the headlight lens and remove oxidation. Ensure the lens remains wet while using the Polishing Pad.

PRODUCT APPLICATION (cont.)

SURFACE PREPARATION (cont.)

The oxidation coming off the lens will appear as a brownish colored liquid; continue to rub until this visual indicator is no longer present.

IMPORTANT: Do not allow the Polishing Pad to come into contact with painted surfaces as it may scratch these surfaces.

Re-wet the headlight lens and use the gray side of the Professional Lens Polishing Pad to further polish the headlight lens.

Dry the lens thoroughly with the included microfiber towel and inspect the surface to ensure oxidation has been removed. If not, repeat steps above on any missed spots. When you can see through the lens while wet, you are ready to apply Wipe New. Ensure all lenses are 100% dry prior to proceeding to application.

APPLICATION

Put on the chemical resistant gloves and ensure that you are in a well-ventilated area. Make sure headlight lenses are completely dry. Tear open the Wipe-It packet, pull out the applicator cloth and carefully wipe the lens ONE TIME in a single wipe, from one row to the next, with a slight overlap (like mowing a lawn) until the surface is completely coated. Be careful to not get any Wipe New on the surrounding paint. If treating multiple lenses, do so before the Wipe-It dries out. If Wipe New comes in contact with an unintended surface such as paint; wipe it off immediately with a dry cloth. Within an hour of application (while still undergoing initial cure), acetone may be used to remove Wipe New from a painted surface, but not from plastic or any non-metal surface. Because acetone can damage vehicle parts or paint, it should be used only after checking with the vehicle manufacturer or a Certified Paint Professional as to how to best apply or remove product. After Wipe New has cured, removing it will require the use of a fine polishing compound or high grit automotive sandpaper.

DRY TIME

The headlights will dry to the touch in about 1 hour. Do not allow treated lenses to come in contact with direct moisture (rain, dew, etc.) for 24 hours. Store excess product in a cool, dry place.

COVERAGE

One Wipe-It contains enough Wipe New to treat the exterior of multiple headlight lenses.

DISPOSAL

When finished, set the applicator cloth in a location out of the reach of children and allow it to dry completely prior to discarding (a few hours).

	TECHNICAL DATA	WNW-02
<small>*TRUSTED QUALITY SINCE 1921*</small> RUST-OLEUM® WIPE NEW	WIPE NEW® HEADLIGHT RESTORE	

PHYSICAL PROPERTIES

		HEADLIGHT RESTORE
Resin Type		Siloxane Polymer
Pigment Type		NA
Volatile Organic Compounds		None
Practical Coverage at Recommended DFT		Contains enough to treat the exterior of multiple headlight lenses.
Dry Times at 70-80°F (21-27°C) and 50% Relative Humidity	Touch	1 hour
	Recoat	NA
	Full Cure	24 hours
Shelf Life		5 years
Flash Point		56°F (13°C)
Safety Information		For additional information, see SDS

The technical data and suggestions for use contained herein are correct to the best of our knowledge, and offered in good faith. The statements of this literature do not constitute a warranty, express, or implied, as to the performance of these products. As conditions and use of our materials are beyond our control, we can guarantee these products only to conform to our standards of quality, and our liability, if any, will be limited to replacement of defective materials. All technical information is subject to change without notice.