







(A) x2



(B) x1



(C) x2



(G) x12


(H) x12

(I) x12

(J) x12

(K) x4

(L) x4




(F) x40




Parts List

Included Tools

(A) Tower Frame	(E) Caster	(I) Lock Washer (3/8")
(B) Base Frame	(F) Shelf Arm	(J) Nut (3/8 - 16)
(C) Caster Tube	(G) Bolt (3/8 - 16, 2.5" L)	(K) Lock Washer (1/2")
(D) Caster w/ Brake	(H) Washer (3/8")	(L) Nut (1/2 - 13)




1



- Attach base frame (B) to caster tubes (C) using four bolts (G), washers (H), lock washers (I), and nuts (J). Secure casters (E) and locking casters (D) to frame using lock washers (K) and nuts (L)


2



- Do not exceed 25 lbs per shelf arm when centered.
- Do not exceed 15 lbs per shelf arm when extended.

RECOMMENDED ACCESSORY

Add 40 additional shelf arms with the PDRAD Shelf Arm Accessory (PDRAD.SHF).



- Attach tower frames (A) to base frame (B) using four bolts (G), washers (H), lock washers (I), and nuts (J). Slide shelf arms (F) into towers and arrange according to workflow and material size.