



NOTES:

1. TO INSPECT ASSEMBLY, FOLLOW FIRST ARTICLE AND IN PROCESS INSPECTION SHEET.
2. APPLY LIGHT FILM OF DOW CORNING 111 SILICONE COMPOUND
3. APPLY LOCTITE 680



BILL OF MATERIAL (CURRENT LEVEL)

ITEM	PT/ASSY	DESCRIPTION	TYPE	QTY.
1	2-187	SINGLE HOLE CROSS BAR ASSEMBLY	ASSEMBLY	1
2	3-572	SPOUT ASM	ASSEMBLY	1
3	10331	BONNET FOR 933, 934	PART	2
4	2-173	CROSS HANDLE ASSEMBLY W/O BUTTON	ASSEMBLY	2
5	1-107	COLD BUTTON ASSEMBLY W/ ADHESIVE	ASSEMBLY	1
6	1-108	HOT BUTTON ASSEMBLY W/ ADHESIVE	ASSEMBLY	1
7	91046	O-RING, #2-118, EPDM, 65-75 DURO	PART	1





-	D	EN-4300hh	04/12/21	R.S.
-	C	EN-2896c	05/20/16	J.A
-	B	EN-2643	01/15/16	J.M
-	A	EN-1326	09/02/09	-
-	-	RELEASED	-	-
ZONE	REV	DESCRIPTION	DATE	APPROVED

COPYRIGHT 2005 BRASSTECH, INC. THESE DRAWINGS AND THE DESIGNS DEPICTED HEREIN ARE THE PROPRIETARY PROPERTY OF BRASSTECH. ANY USE OR REPRODUCTION IS SUBJECT TO THE EXPRESS APPROVAL OF BRASSTECH. UNAUTHORIZED USE IS STRICTLY PROHIBITED. ALL RIGHTS RESERVED.

TESTING	-	-	-
ASSEMBLY	-	-	-
PLATING	-	-	-
POLISHING	-	NEXT ASSY	USED ON
MACHINING	-	APPLICATION	
TOOLING FIXTURE #	REMOVE ALL BURRS AND SHARP EDGES		

UNITS ARE: INCHES [MM]			
TOLERANCES ARE:			
FRACTIONS	DECIMALS	ANGLES	
±1/16"	.X ±.1 [2.5]	±1°	
	.XX ±.06 [1.5]		
(X.XXX) DENOTES CRITICAL DIMS. ALL THREADS ARE CRITICAL			
DRAWN	AMARISH	05/20/16	
CHECKED	JINSON	05/20/16	
APPROVED	J.A	05/20/16	

BRASSTECH		2001 CARNEGIE AVE. SANTA ANA, CA 92705 (949) 417-5207	
INCORPORATED			
BAR FAUCET			
DWG NO.		REV	
938		D	
SCALE	REF.	SHEET	OF
.225	-	1	2



BRASSTECH		2001 E. CARNEGIE AVE. SANTA ANA, CA 92705 (949) 417-5207	
DWG NO.	938	REV	D
SCALE	.250	REF.	-
		SHEET	2 OF 2