










W913808740121



⚠ ⚠ DANGER
HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH
 Disconnect all power before servicing equipment.
 Failure to follow these instructions will result in death
 or serious injury.



Ø 3 mm Ø 0.118 in.				Ø 3 mm Ø 0.118 in.			
1, ...2,	1, ...4	1, ...6,	0, ...1,	0, ...2,	1, ...2,	0,34 ...1	0, ...1, 1...1,
A C			10 - 3	A 60	14 - 1 C	A 60	1 - 20 C
TR			3	TR		3	TR