

PARTS LIST

GRAINGER #16Y918

PROLINE #W/HD/ST6030

Required

1	#HD-LA30-L-H11	LEFT LEG ASSEMBLY 27.75" X 27.5"
1	#HD-LA30-R-H11	RIGHT LEG ASSEMBLY 27.75" X 27.5"
1	#HD-FRC60-H11	FRONT RAIL 2" X 2" X 1" X 51"
1	#HD-BR60-H11	BACK RAIL 1.5" X 8" X 1" X 51"
1	#WT-LURS60-H11	WELDING TABLE LURS 2" X 2" X 55"
4	#2X2NSRTS	2" SQUARE THREADED INSERTS
4	#GLDS	WHITE NYLON GLIDES
10	#TTBC	TURNTABLE BALL CLIPS 1" X 1.25"
1	#WS6030.25ST	WELDING TABLE WORKSURFACE 60" x 30" X .25" STEEL PLATE
1	#WT-HDWKT	WELDING TABLE HARDWARE KIT

1

#WT-INST

WELDING TABLE ASSEMBLY INSTRUCTIONS