




ITEM	DESCRIPTION	PART NO.
1	BACK PANEL 1117LN	0410000218
2	GRILLE 1117L P/N	0002626651
** 3	MOUNTING FRAME	MTGFR.LG
4	BUTTON	PBA6
5	BUBBLER HEAD	5703M
6	STRAINER ASSY	6462
7	TRAP	0005982900
8	REMOTE CHILLER	HCR8
9	SPANNER WRENCH	0006983506
10	BOTTOM PLATE	PBM1107
11	KEY HEX F/PINNED HEX	0002981127
12	VALVE REPAIR KIT	VRK5874



** REQUIRED - SOLD SEPARATELY



1 REMOVE INSERT WITH 5/16 HEX SOCKET (NOT SUPPLIED)



DETAIL A
ROTATED 90° INTO VIEW



NOTES:

1 ENSURE TUBE IS DISCONNECTED FROM PUSH BUTTON VALVE BODY PRIOR TO REMOVAL. APPLY ONE DROP OF LOCTITE 222MS TO NOZZLE THREADS PRIOR TO FASTENING BACK ONTO BUBBLER HEAD. RE-ATTACH TUBE TO VALVE.

PARTS BREAKDOWN

WHEN ORDERING PARTS PLEASE SPECIFY MODEL NUMBER.

			1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWS.CO.COM WEBSITE: WWW.HAWS.CO.COM		
ECN NO. _5671	REVISED PER ECN: 5671	BY DP	MODEL(S)	PART NUMBER	
DRAWN DP	DATE 03/23/21	CHKD FV	H1117LN.8	0510001192	
APPROVED DP	DATE 06/21/21		SCALE: N/A	DRAWING TYPE: PARTS BREAKDOWN	REVISION 2
				SIZE: A	SHEET 1 OF 1